





## Vehicle History Report

### CHRYSLER 300C 2014

Vehicle reference:

**2C3CCABG5EH377726**

Body type:

Sedan

Gearbox type:

Automatic

Engine size:

3604 cm<sup>3</sup>

Fuel type:

Petrol, LPG

Combustion engine power:

215 kW / 292 hp

Drive:

Rear

Report created on: 2026-01-18 at 16:56:59



Scan QR code for [current version](#)



[Get American report!](#)



Located in Poland



Vehicle age

**12 years**

Imported vehicle



### How to use this report

This history is based on data reported to us and available upon request. Gaps and errors cannot be excluded. Use CARFAX in combination with a test drive and inspection by experts. We process personal data only in accordance with applicable regulations. Conclusions on owners are not possible at any time.



#### Quick Check

##### Damage

This vehicle has had a damage. Please check with the seller if it has been repaired in the meanwhile, or have it inspected by a mechanic before purchasing.

● **Damage**

##### Mileage

Throughout this vehicle's history, we were provided both km and miles as the odometer reading unit and inconsistencies were identified.

● **Mixed units**

<p><b>Stolen</b> Not reported stolen</p>	<p>● No issues reported</p>
<p><b>Identity check</b> Not reported scrapped</p>	<p>● No issues reported</p>
<p><b>Import</b> Vehicle imported from United States</p>	<p>● Import</p>
<p><b>Motor insurance</b> Vehicle insured</p>	<p>● No issues reported</p>
<p><b>Registration status</b> Vehicle registered in Poland</p>	<p>● No issues reported</p>

**Damage Overview**

2018-06-12 Damage reported



**Details:**  
Check US history for more details on this damage.

**Reported on:**  
2018-06-12  
**Reported in:**  
United States


2018-07-16 Damage reported



**Details:**  
Check US history for more details on this damage.

**Reported on:**  
2018-07-16  
**Reported in:**  
United States

2019-08-27 Damage reported



**Damaged area:**

- Front
- Left
- Left front
- Left rear
- Right front


**Damage type/cause:**  
Not available

**Estimated repair costs:**  
PLN 29,000 - PLN 30,000


**Damaged components:**

- Body parts
- Windshield / Glass
- Upholstery

**Reported on:**  
2019-08-27  
**Reported in:**  
Poland



### 2024-03-04 Damage reported



**Damaged area:**

- Left
- Left rear
- Rear

**Damage type/cause:**

Not available

**Estimated repair costs:**

PLN 5,000 - PLN 6,000

**Damaged components:**

- Body parts

**Reported on:**

2024-03-04

**Reported in:**

Poland

### Damage Glossary


**Damage**

Damage refers to any harm or impairment to a vehicle's physical components, affecting its appearance, functionality, or safety. Damage can range from cosmetic issues like scratches and dents to severe structural problems. It can be caused by collisions, weather events, vandalism, or other incidents.

### Mileage Check

**i Mixed units:** Throughout this vehicle's history, we were provided both km and miles as the odometer reading unit. One mile is equal to 1.6 km. Check the history section below to better understand if any discrepancies are due to possible manipulation or incorrect conversion of units.

### Owners **BETA**



**Owner(s) in United States and potentially in other countries**

Check US history for more details on owners in United States



**Owner 1 in Poland**


Purchase year:	<b>2019</b>
Length of use:	<b>4 years 8 months</b>
Type of owner:	<b>Private individual</b>
Damage reported on:	<b>2024-03-04</b>

**Owner 2 in Poland**

Purchase year:	<b>2024</b>
Type of owner:	<b>Private individual</b>

**History information**

Date	Mileage	Event
2014-01-01		First registration abroad
2014-11-25	13 mile 21 km	Odometer reading reported
2016-03-07	16,739 mile 26,939 km	Odometer reading reported
2016-03-12	17,039 mile 27,422 km	Odometer reading reported
2016-03-23	17,114 mile 27,542 km	Odometer reading reported
2016-05-16	22,075 mile 35,526 km	Odometer reading reported

2016-10-19	32,352 mile 52,065 km	Odometer reading reported
2018-06-12		Damage reported in United States
2018-07-16		Damage reported in United States
2019-03-07	52,107 mile 83,858 km	Odometer reading reported
2019-03-25		Insurance claim reported in United States Salvage title was issued in United States
<div style="border: 1px solid red; padding: 10px;"> <p> <b>Salvage Title</b></p> <p>This vehicle had a Salvage title issued in the USA. Check the condition of the vehicle with a mechanic before purchasing.</p> </div>		
2019-05-04		Imported from United States to Germany
2019-08-27	52,108 km	Damage reported in Poland
2019-10-01	85,972 km	Inspected in Poland Inspection type: regular Inspection passed
2019-10-08		Imported from United States to Poland Registered in Szamotuły, Poland New owner reported Owner type: private individual Located in Szamotuły, Powiat szamotulski, Wielkopolskie, Poland
2020-09-29	90,897 km	Inspected in Poland Inspection type: regular Inspection passed
2021-09-28	95,356 km	Inspected in Poland Inspection type: regular Inspection passed
2022-09-28	99,354 km	Inspected in Poland Inspection type: regular Inspection passed
2023-09-28	103,994 km	Inspected in Poland Inspection type: regular Inspection passed
2024-03-04		Damage reported in Poland
2024-06-17		New owner reported Owner type: private individual Located in Szamotuły, Powiat szamotulski, Wielkopolskie, Poland
2024-09-18	112,351 km	Inspected in Poland Inspection type: regular

Inspection passed		
2025-07-02		Vehicle insured Liability insurance valid until 2026-07-01
2025-09-10	122,477 km	Inspected in Poland Inspection type: regular Inspection passed Inspection valid until 2026-09-10
Based on data reviewed from 22 countries in Europe and North America		

## Technical details

### Engine and performance

Fuel type	Petrol, LPG
Combustion engine power	215 kW / 292 hp

### Weight

Curb weight	1,790 kg
Max payload	524 kg
Gross vehicle weight	2,314 kg

### Dimensions

Wheelbase	3,053 mm
-----------	----------

### Other information

European vehicle category	M
Number of doors	4
Number of seats	5

### CARFAX Glossary

**Imported vehicle**  
A vehicle that has been imported from another country

**Model year**  
This term is defined by the manufacturer but it is typically the year the vehicle is built. If the model year does not appear on the CARFAX report, it is because the manufacturer did not include this information in the VIN. Model year can normally be determined by the vehicle age.

**Number of records**  
A CARFAX record refers to a specific incidence and date in the history of the vehicle. Please note that the history of younger vehicles tends to have fewer entries. CARFAX continuously works on getting more data sources and historical information in order to enrich the report

**Quick Check**  
A snapshot of the information CARFAX has abstracted from our extensive database to determine whether a vehicle has been reported stolen, reported scrapped, publicly imported or ever used for non-personal purposes. This summary is based upon all the information supplied to

CARFAX from various sources. Additional information about this vehicle, including these potential problems, may exist and may not have been reported to CARFAX.

**Vehicle reference**

User-provided value to identify the vehicle during the CARFAX Vehicle History Report retrieval process and to confirm vehicle identity on the report itself.



---

CARFAX is an international provider of vehicle histories with the goal of making the used car market more transparent and our roads safer worldwide.

**Contact**

[Press](#)

[Careers](#) We are hiring

[Terms and conditions](#)

[Legal information](#)

[Privacy Notice](#)

[Cookie Settings](#)

---

Copyright © 2026 CARFAX. All rights reserved. CARFAX is a registered trademark of CARFAX. All other trademarks are the property of their respective owners.